



Model GA4570 Parts List

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty	Unit	
1	621706-3	FIELD 115V	1	PC.	
2	457791-8	BAFFLE PLATE	1	PC.	
3	421868-5	LABYRINTH RUBBER RING 19	1	PC.	
4	211021-9	BALL BEARING 607LLB	1	PC.	
5	681636-0	INSULATION WASHER	1	PC.	
6	515567-0	ARMATURE ASS'Y 115V	1		
	D10	INC. 4,5,7			
7	240076-7	FAN 56	1	PC.	
8	136170-0	GEAR HOUSING COVER ASS'Y	1	PC.	
	D10	INC. 9			
9	213407-3	O RING 26	1	PC.	
10	210042-8	BALL BEARING 629LLB	1	PC.	
11	226950-3	SPIRAL BEVEL GEAR 10	1	PC.	
12	252186-8	HEX. NUT M6	1	PC.	
17	136209-9	GEAR HOUSING ASS'Y	1	PC.	
	D10	INC.18-21			
18	459967-3	LEVER	1	PC.	
19	961017-7	STOP RING E-3	1	PC.	
20	232576-1	TORSION SPRING 5	1	PC.	
21	256935-5	HEADED PIN 4	1	PC.	
22	266361-0	TAPPING SCREW 4X30	4	PC.	
23	327460-4	SHAFT	1	PC.	
24	961104-2	RETAINING RING S-24	1	PC.	
25	226951-1	SPIRAL BEVEL GEAR 37	1	PC.	
26	962201-7	RETAINING RING (INT) R-42	1	PC.	
27	210208-0	BALL BEARING 6905DDW	1	PC.	
28	213622-9	O RING 45	1	PC.	
29	136348-5	BEARING BOX ASSY	1		
	D10	INC. 28			
30	911138-5	P.H.SCREW M4X20 WITH WR	4	PC.	
36	127746-4	WHEEL COVER 115 ASSEMBLY	1		
	C10	213009-5	O RING 4	1	PC.
	C20	265180-1	PAN HEAD SCREW M5X16	1	PC.
37	327459-9	RING 25	1	PC.	
38	127428-8	SPINDLE ASSEMBLY	1	PC.	
39	266007-8	TAPPING SCREW BIND PT 3X10	4	PC.	
40	643516-8	BRUSH HOLDER	2	PC.	
41	CB325	CARBON BRUSH SET CB-325 (195001-2)	1	SET	
43	650579-7	SWITCH 1246.3223	1	PC.	
44	687063-9	CORD CLAMP	1	PC.	
45	265995-6	TAPPING SCREW 4X18	2	PC.	
47	682559-5	CORD GUARD 8	1	PC.	
48	664893-5	POWER SUPPLY CORD #18-2-2.5	1	PC.	
49	419566-3	SWITCH KNOB	1	PC.	
50	140Y30-0	MOTOR HOUSING COMPLETE	1		
	C10	8024H9-6	CAUTION LABEL	1	
52	233121-5	COMPRESSION SPRING 4	1	PC.	
53	418727-2	SWITCH LEVER	1	PC.	
54	418726-4	REAR COVER	1	PC.	

55	265995-6	TAPPING SCREW 4X18	1 PC.
56	266345-8	TAPPING SCREW 4X80	2 PC.
57	857U68-1	GA4570 NAME PLATE	1
A01	158237-4	GRIP 36 COMPLETE	1 PC.
A02	E-00430	GRIDING WHEEL INOX 115 X-LOCK	1 PC.